



SUC 300 E




**Reservedelsliste
Spare parts list
Ersatzteilliste
Onderdelenlijst
Liste de pièce de rechange
Lista dei pezzi di ricambio**

SUC 300 E



3

SUC 300 E



5

SUC 300 E





Fig.	Part no.	Pieces	Notes
1	100 302 028	2	Bolt with nut M12 x 60 mm
2	100 332 005	4	Star washer M12
3	121 122 039	2	
4	100 315 014	4	Nut M16
5	100 331 008	4	Flat washer M16
6	100 501 020	1	Motor 180 M2-22 kW-B3-3x400 V-50 Hz-2935 rpm
7	100 315 016	2	Nut M12
8	100 315 016	4	Nut M12
9	100 332 005	4	Star washer M12
10	100 315 012	4	Nut M8
11	100 332 003	4	Star washer M8
12	121 122 046	1	
15	100 308 004	2	Set screw M10 x 20 mm
16	100 306 015	4	Set screw M8 x 20 mm
17	100 501 002	1	Motor 90 S4-1.5 kW-B3-3x400 V-50 Hz-1410 rpm
18	100 306 017	4	Set screw M8 x 30 mm
19	100 503 134	1	Motor protection starter box 3x400V, 50 Hz
20	100 503 208	1	Motor protection starter box 3x440V, 60 Hz
22	100 306 067	4	Set screw M8 x 15 mm
	121 122 213	1	
23	100 332 003	4	Star washer M8
24	100 315 012	4	Nut M8
25	100 306 015	4	Set screw M8 x 20 mm
30	121 132 067	1	
31	121 000 333	6	
32	121 000 163	1	
33	100 333 004	4	Split pin ø5 x 30 mm
34	100 412 003	3	Wheel 12 x 3
35	121 000 746	1	
36	100 323 020	1	Flat washer ø60 x 33 x 5 mm
40	100 315 012	2	Nut M8
41	100 331 005	2	Flat washer M8
42	100 306 015	2	Set screw M8 x 20 mm
43	100 306 037	1	Bolt M10 x 65 mm
44	121 132 066	1	
45	100 316 004	1	Lock nut M10
46	100 306 015	2	Set screw M8 x 20 mm
47	100 332 003	4	Star washer M8
48	100 315 012	4	Nut M8
50	100 315 013	2	Nut M10
51	100 332 004	2	Star washer M10
52	100 332 003	4	Star washer M8
53	100 315 012	4	Nut M8
54	121 122 002	1	
55	100 306 043	4	Set screw M12 x 30 mm
56	121 122 044	1	
57	100 331 007	4	Flat washer M12
60	100 304 035	2	Set screw M12 x 45 mm
61	100 306 015	6	Set screw M8 x 20 mm
63	100 332 003	6	Star washer M8
64	100 315 012	6	Nut M8
65	121 123 230	1	
66	100 322 005	1	Stop screw M10 x 15/16 mm
67	121 122 042	1	V-belt pulley SPA 225 with 4 grooves, bore ø48 mm, 50 Hz
	121 123 288	1	V-belt pulley SPA 190 with 4 grooves, bore ø48 mm, 60 Hz
68	100 403 017	4	Raw edge moulded notch V-belt SPA-1800, Set 4
69	121 123 232	1	
70	100 321 010	4	Torx screw M5 x 12 mm
71	121 000 686	4	
72	121 000 402	4	
73	121 122 043	1	V-belt pulley SPA 160 with 4 grooves, bore ø45 mm
75	100 332 003	2	Star washer M8
76	100 315 012	2	Nut M8
77	121 122 132	1	
78	100 322 001	2	Stop screw M6 x 10 mm
79	121 122 053	1	V-belt pulley SPA 85 with 1 groove, bore ø24 mm, 50 Hz
	170 030 044	1	V-belt pulley SPA 71 with 1 groove, bore ø24 mm, 60 Hz
80	121 122 052	1	V-belt pulley SPA 212 with 1 groove, bore ø18 mm
81	100 403 018	1	Raw edge moulded notch V-belt A37.5
82	121 000 402	4	
83	121 122 134	1	
84	121 000 686	4	
85	100 321 010	4	Torx screw M5 x 12 mm

SUC 300 E



9

