

VIBROCULTIVATOR

SPARE PARTS LIST



FIG.	CODE	NOTES	FIG.	CODE	NOTES
1	190132	Pin linkage bolt	15	313002	Bearing 207
2	190121	Pin bolt	16		
3	190138	Hair pin clip (18mm)	17		
4	-	Upper frame	18		
5	140906	"Bellota" arm			
6	-	Roller support			
7	-	Main frame			
8	Cil.Vib.	Hydraulic cylinder			
9	190141	Pin bolt roller (28mm)	1b		
10	-	Arm roller	1c		
11	-	Rake support (vibrocultivator with rake)	1d		
12	442001	Outside disk (410 mm)	1e		
13	J2315	Inner washer (400 mm)			
14	-	Roller frame			

➤ **GENERAL SAFETY ADVICE**

Let's show a series of norms in order to handle the equipment in the maximum secure way. Read these norms carefully and bear them always in mind while working with the equipment.

- 1 Before working with the Vibrocultivator for the first time, read the current user manual carefully. Make sure all the potential users read it. The equipment must be used with care. The lack of attention is frequently a major reason behind accidents.
- 2 Identify the meaning of every single equipment sticker; keep an eye on them.
- 3 Before starting the tractor with the Vibrocultivator, make sure all the rivets as well as security bolts are perfectly placed. If you have an hydro-pneumatic Vibro check whether there are oil leaks in the hydraulic circuit.
- 4 No modification will be made on the Vibrocultivator without the manufacturer written permission. Every reform and assembly of non - original pieces on the equipment without such consent implies the loss of the guarantee as well as the cancellation of the manufacturer responsibility assumed on the certificate.

➤ **WARRANTY**

All of our machines are guaranteed against any manufacture defects for one year from the date of delivery, this last guarantee condition should be recognized by JYMPA in order to be effective, in which case, the assembly, disassembly, transport and shipping expenses shall be on the user's account, while the new spare parts should be on our company's charge

Machines attached to non recommended power tractors as well as equipment modified by the client are excluded from this guarantee .









JYMPA Maquinara Agrícola shall not admit any claim because of personal accidents caused by either misuse or non compliance with the security norms set up

➤ STICKERS EXPLANATION

Stickers have been placed in some points considered particularly dangerous in order to inform about the kind of danger the user may be.

Keep the stickers in good state. In case they are worn out, please proceed to ask the manufacturer or the dealer for new ones and replace them immediately.

The warning stickers are

		<p>Read the instructions manual carefully.</p>			<p>Injection danger or pressurized flow projection.</p>
		<p>Do not place yourself on the Vibro.</p>			<p>Special care if located between the tractor and equipment..</p>